



Vehicle Inspection Summary by Superstition Specialty Cars, LLC, 602-570-0414

As most collector car sales are deemed 'as-is', this report represents a visual inspection of a vehicle to verify condition and help with your purchasing decision. This is not a value assessment, or an in-depth investigation, or estimate for repairs, nor does this report act as a warranty on the vehicle's condition.

S = Satisfactory appearance of regular wear and tear, R = Requires troubleshoot/repair

Name / Company Contact Number XXX-XXX-XXXX
Email Address XXXXXXXX@yahoo.com
Year 1970 **Make** Plymouth
Model Satellite / GTX **Color** Blue
Body Style Coupe **VIN** RH23GOAxxxxxx
Engine Size / Type 360/408 **Transmission** 727
Drive Type Auto **Mileage**
Inspection Technician Dave **Inspection ID** 20180807_1

ID Number	Test Point Number	Test Point Description	Condition	Comment
Exterior, Body 1				
101	1	General Body Condition	S R N/A	
102	2	Body Modifications	S R N/A	
103	3	Body Panel Fit	S R N/A	
104	4	Paint Condition	S R N/A	
105	5	Rust/Corrosion	S R N/A	Original door jambs
106	6	Door Condition	S R N/A	
107	7	Door Weather stripping	S R N/A	
108	8	Door Handles / Locks	S R N/A	
109	9	Front Fenders	S R N/A	
110	10	Rear Fenders	S R N/A	
111	11	Hood Condition	S R N/A	
112	12	Roof / Pillars / Roof Rack	S R N/A	
113	13	Trunk / Hatchback	S R N/A	
114	14	Front Bumper	S R N/A	
115	15	Rear Bumper	S R N/A	
116	16	Fuel Door Operation / Gas Cap	S R N/A	
117	17	Side Mirrors	S R N/A	
118	18	Trunk Bed / Tailgate	S R N/A	
Exterior, Glass / Trim 2				
201	19	Front Windshield Condition	S R N/A	
202	20	Rear Windshield Condition	S R N/A	
203	21	Door Glass Condition	S R N/A	
204	22	Grill	S R N/A	
205	23	Body Trim / Moldings	S R N/A	Belt line trim removed, recesses mildly visible at close range.
206	24	Chrome Condition	S R N/A	
207	25	Convertible Top	S R N/A	



Vehicle Inspection Summary by Superstition Specialty Cars, LLC, 602-570-0414

As most collector car sales are deemed 'as-is', this report represents a visual inspection of a vehicle to verify condition and help with your purchasing decision. This is not a value assessment, or an in-depth investigation, or estimate for repairs, nor does this report act as a warranty on the vehicle's condition.

S = Satisfactory appearance of regular wear and tear, R = Requires troubleshoot/repair

208	26	Wipers Front / Rear	S R N/A	
209	27	Antenna / Operation	S R N/A	
Exterior, Lighting 3				
301	28	Headlights - High / Low	S R N/A	
302	29	Fog Lights	S R N/A	
303	30	Side Marker Lamps	S R N/A	
304	31	Tail Lights	S R N/A	
305	32	Turn Signals	S R N/A	
306	33	Brake Lights / Center Light	S R N/A	
307	34	Emergency Road Hazzard Lights	S R N/A	
308	35	Reverse Lights	S R N/A	
309	36	License Lights	S R N/A	
310	37	Other Lights	S R N/A	
Interior, Condition 4				
401	38	General Condition / Odor / Mildew	S R N/A	
402	39	Interior Modifications	S R N/A	
403	40	Headliner	S R N/A	
404	41	Front Seat / Covers	S R N/A	
405	42	Rear Seat / Covers	S R N/A	
406	43	Seat Belts	S R N/A	
407	44	Headrests	S R N/A	
408	45	Front Carpet / Floor Mats	S R N/A	
409	46	Rear Carpet / Floor Mats	S R N/A	
410	47	Cargo / Trunk Carpet	S R N/A	
411	48	Door Sill Plates	S R N/A	
412	49	Door Trim Panels	S R N/A	Armrests are original condition
413	50	Door Glass / Tint	S R N/A	
414	51	Dashboard	S R N/A	Some normal wear present
415	52	Interior Trim / Molding	S R N/A	
416	53	Airbag Covers	S R N/A	
417	54	Glove Box Operation	S R N/A	
418	55	Spare Tire	S R N/A	
419	56	Tire / Jack / Tools	S R N/A	
420	57	Toolkit Complete	S R N/A	
Interior, Convenience / Controls, 5				
501	58	General Condition	S R N/A	
502	59	Owners Manuals	S R N/A	
503	60	Gearshift Operation	S R N/A	
504	61	Parking Brake Control	S R N/A	
505	62	Hood Release	S R N/A	



Vehicle Inspection Summary by Superstition Specialty Cars, LLC, 602-570-0414

As most collector car sales are deemed 'as-is', this report represents a visual inspection of a vehicle to verify condition and help with your purchasing decision. This is not a value assessment, or an in-depth investigation, or estimate for repairs, nor does this report act as a warranty on the vehicle's condition.

S = Satisfactory appearance of regular wear and tear, R = Requires troubleshoot/repair

506	63	Tilt Steering	S R N/A	
507	64	Seat Position Adjusters	S R N/A	
508	65	Power Seat Switch / Motor	S R N/A	
509	66	Power Window Switch / Motor	S R N/A	
510	67	Door Locks / Power Switches	S R N/A	
511	68	Power Mirrors	S R N/A	
512	69	Sunroof	S R N/A	
513	70	Sun visor Vanity Mirrors	S R N/A	
514	71	Windshield Wiper Controls	S R N/A	
515	72	Defogger / Defogger Light	S R N/A	
516	73	Horn	S R N/A	
517	74	Remote Fuel Door Release	S R N/A	
518	75	Remote Trunk Release	S R N/A	
519	76	Cigarette Lighter	S R N/A	
520	77	Remote Key FOB	S R N/A	
521	78	Alarm	S R N/A	
Interior, Instruments / Lighting, 6				
601	79	Gauges	S R N/A	
602	80	Odometer	S R N/A	
603	81	Dash / Instrument Lighting	S R N/A	
604	82	Check Engine Light	S R N/A	
605	83	Airbag Warning Light	S R N/A	
606	84	ABS Warning Light Operation	S R N/A	
607	85	Clock	S R N/A	
608	86	Dome Light	S R N/A	
609	87	Rear View Mirror / Compass	S R N/A	
610	88	Sun visor Vanity Lights	S R N/A	
611	89	Trunk Light	S R N/A	
612	90	Warning Lights, Other	S R N/A	
Interior, A/C & Heating, 7				
701	91	A/C Operation / Temperature	S R N/A	
702	92	Heater Operation / Temperature	S R N/A	
703	93	Climate Control Operation	S R N/A	
704	94	Blower Speeds / Operation	S R N/A	
705	95	A/C Registers	S R N/A	
706	96	Seat Heater / Cooler Operation	S R N/A	
707	97	Radio Operation / Condition	S R N/A	
708	98	Speaker Operation / Condition	S R N/A	
709	99	CD / DVD Operation	S R N/A	
710	100	Navigation System	S R N/A	



Vehicle Inspection Summary by Superstition Specialty Cars, LLC, 602-570-0414

As most collector car sales are deemed 'as-is', this report represents a visual inspection of a vehicle to verify condition and help with your purchasing decision. This is not a value assessment, or an in-depth investigation, or estimate for repairs, nor does this report act as a warranty on the vehicle's condition.

S = Satisfactory appearance of regular wear and tear, R = Requires troubleshoot/repair

711	101	Back Up Camera	S R N/A	
712	102	Rear Entertainment System	S R N/A	
Engine, Under Hood, 8				
801	103	Engine / Under hood Modifications	S R N/A	
802	104	Hood Release Operation	S R N/A	
803	105	Hood Latch Operation	S R N/A	
804	106	Hood Hinges / Struts	S R N/A	
805	107	Hood Insulation	S R N/A	
806	108	Engine Emissions Placard	S R N/A	
807	109	Engine Emissions System	S R N/A	
808	110	Battery Condition / Battery Hold Down	S R N/A	
809	111	Alternator / Generator	S R N/A	
810	112	Engine Wiring	S R N/A	
811	113	Engine Leaks	S R N/A	
812	114	Cooling System / Radiator / Cap	S R N/A	
813	115	Fuel System	S R N/A	Leaking at sending unit
814	116	Radiator Coolant Condition	S R N/A	
815	117	Heater Hoses / A/C Hoses	S R N/A	
816	118	Drive Belts Condition	S R N/A	
817	119	Air Cleaner / Filter	S R N/A	
818	120	Engine Oil Condition	S R N/A	Fuel present
819	121	Engine Oil Sludge	S R N/A	
820	122	Transmission Fluid Condition	S R N/A	
821	123	Power Steering System	S R N/A	
822	124	Brake Master Cylinder Fluid Check	S R N/A	
823	125	Windshield Washer Fluid	S R N/A	
Drive Train and Chassis, 9				
901	126	Chassis / Undercarriage Condition	S R N/A	
902	127	Chassis / Undercarriage Modifications	S R N/A	
903	128	Frame / Unibody Condition	S R N/A	
904	129	Exhaust System	S R N/A	
905	130	Suspension System	S R N/A	
906	131	Shock Absorbers	S R N/A	
907	132	Steering Condition	S R N/A	
908	133	Transmission / Cooler Line Leaks	S R N/A	
909	134	Brakes	S R N/A	
910	135	Tire Condition and Tread Depth	S R N/A	
911	136	Wheel Condition	S R N/A	
Test Drive, 10				
1001	137	Test Drive Length and Speed	S R N/A	



Vehicle Inspection Summary by Superstition Specialty Cars, LLC, 602-570-0414

As most collector car sales are deemed 'as-is', this report represents a visual inspection of a vehicle to verify condition and help with your purchasing decision. This is not a value assessment, or an in-depth investigation, or estimate for repairs, nor does this report act as a warranty on the vehicle's condition.

S = Satisfactory appearance of regular wear and tear, R = Requires troubleshoot/repair

1002	138	Cold / Hot Start Quality	S R N/A	
1003	139	Starter Function Quality	S R N/A	
1004	140	Engine Idle Quality	S R N/A	
1005	141	Engine Noise / Knocks / Rattles	S R N/A	
1006	142	Engine Smokes / Excessive Blow by	S R N/A	
1007	143	Normal Engine Operating Temperature	S R N/A	
1008	144	Engine Acceleration / Power Check	S R N/A	
1009	145	Exhaust Noise Level	S R N/A	
1010	146	Transmission / Clutch Operation	S R N/A	
1011	147	Transmission Shift / Gears Operate Smoothly	S R N/A	
1012	148	Steering Wheel Centered	S R N/A	
1013	149	Steering System Operation	S R N/A	
1014	150	Vehicle Alignment / Tracking Check	S R N/A	
1015	151	Road Vibration	S R N/A	
1016	152	Tire Noise	S R N/A	
1017	153	Suspension / Handling Quality	S R N/A	
1018	154	Brake Operation	S R N/A	
1019	155	Parking Brake Operation	S R N/A	
1020	156	Speedometer / Odometer Operation	S R N/A	
1021	157	Wind Noise	S R N/A	
1022	158	Squeaks / Rattles	S R N/A	

Inspection Summary

Photographs of all inspection points, and Test Point identifications can be found here:

<https://www.flickr.com/gp/s9santoro/5F4U7f>